# Real Time Monitoring of RF System Performance

Presented By: Dan Glavin



#### AGENDA

- Live Monitoring: Why it is Necessary
- Minor Field Issues
- Collateral Damage
- Current Practices
- Next Generation Approach
- Results


# Live Monitoring: Why it is Necessary



Video Credit to YouTube User apsparky

### Live Monitoring: Why it is Necessary

- Transmission line is a vital component to delivering adequate power to a broadcast system
- Components and joints can become susceptible to failures over time
- Each component is handled by several people beginning with manufacturing and ending with installation









Trusted for Decades. Ready for Tomorrow.

- Damaged in transit or installation
- Discontinuity in contact ring creates an area for series arcing
- Series arcing eats away at the brass
- Impedance mismatch increases as metal deteriorates
- Outer-to-outer series arcing evolves into inner-toouter arcing
- End result = Failure



Figure 1: Damaged contact surface

- Components such as O Rings and Teflon insulators can easily be pinched between flanges
- Introduce dielectric between contact surfaces
- Fosters environment for series arcing between outer conductors
- May not be seen on commissioning system sweep



Figure 2: Insulator Crushed Between Transmission Line Flanges

- Carbon will build up over time
- Excessive build up will lead to melting Teflons and could result in fire inside transmission line
- Can cause tremendous trickle-down damage to entire system
- Remediation process is extensive




Figure 3: Carbon Build-Up On Teflon Insulator

- Split connectors reduce the surface area of connectivity
- Arcing will occur between connector and inner conductor
- Changes the effective spacing between inner and outer
- Impedance mismatch that will increase over time



**Figure 4: Split Bullet Anchor Connector** 



Trusted for Decades. Ready for Tomorrow.










Trusted for Decades. Ready for Tomorrow.

- Transmission line bullet connector with
   Teflon insulator disintegrated
- No longer has a stabilizing structure to support centering the inner conductor
- Impedance fluctuation at this joint creates hot-spots



**Figure 5: Melted Teflon Insulator** 

- Inner conductors collapsed and piled up inside vertical TL run
- Pile up caused by connector burn up at fault location
- Creates a domino effect



**Figure 6: Collection of Inner Conductors** 

- Oxidization and melting Teflons result in a collection of soot down stream
- Insulators and connectors that have failed can be seen piled up



Figure 7: Collection of Melted Insulators, Inner Conductors, and Soot

- Contamination is not localized
- Creates a domino effect
- Debris will fall and continue to contaminate transmission line down hill from fault
- The process of remediation is extensive and costly



Figure 8: Debris Littered Throughout Feed System

### The Goal

- Prevent Failures in the Transmission Lines
- Early Detection of Transmission Line Degradation or Frequent Arcing
- Perform Preventive Maintenance During Non-Critical
   Broadcast Windows to Replace Affected Components
- Minimize Downtime and Increase System Reliability
- Reduce Maintenance and Repair Costs



- TDR Measurements
- Forward/Reflected Power
- Arc Detectors

#### **TDR Measurements**

- Performed while off-air and under significantly reduced power during a system's commissioning
- This practice is used to characterize the system and to look for anomalies through broadband and narrow band sweeps
- Provides valuable information by locating faults

#### Forward/Reflected Power Measurements

- Transmitters continually monitor levels of forward and reflected power
- These measurements are used to calculate VSWR and can be displayed by a digital output on the transmitter itself
- This information can influence a system shutdown

#### **Arc Detectors**

- Identify arcing occurrences
- Ability to reduce or discontinue transmitter output power

#### **Shortcomings**

#### **TDR**


- Measures response of system under limited power
- Anomalies can go undetected
- Does not continue to characterize system
- Requires system shut down and field qualified engineer

#### Forward/Reflected Power


- Aggregate response of entire system
- Does not localize fault
- Difficult to interpret

#### **Arc Detectors**


Cannot localize arcing event




Trusted for Decades. Ready for Tomorrow.




Trusted for Decades. Ready for Tomorrow.




Trusted for Decades. Ready for Tomorrow.




Trusted for Decades. Ready for Tomorrow.




Trusted for Decades. Ready for Tomorrow.




Trusted for Decades. Ready for Tomorrow.




Trusted for Decades. Ready for Tomorrow.




Trusted for Decades. Ready for Tomorrow.



Trusted for Decades. Ready for Tomorrow.



Trusted for Decades. Ready for Tomorrow.



Trusted for Decades. Ready for Tomorrow.

### Conclusions

- Minor issues occur due to human error
- Collateral damage occurs when minor issues go undetected
- Current practices play an important role but are outdated
- A Real-Time Time-Domain Monitoring System has been tested and remains in the development stage to meet all broadcaster's needs

# THANKS FOR YOUR TIME!



